

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Posted?
 213

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 27 5 Mer.

Section Corner common to Sections
33, 34, 4, and 3

Corner ~~is not~~ not in ~~its proper~~



State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

142-27			
S 34			
B.T.			

Species W.P. _____

Diameter 20" _____

Bearing N55°W _____

Distance 26 lks _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

P.T. Defant
 Don Rowen

(Signature)

Ass't Leader

(Title)

8/20/40

(Date)

Corner again.

Give any other facts which will aid in finding the


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



Sketch of topographic map corner