

U. S. Department of Agriculture

FOREST SERVICE

T-49

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 27 S. 5 Mer.

M.C. Corner common to Sections

....., 28, and 29

Corner consists of a brass cap (~~rod~~) in place

State condition good

Dimensions above ground 10" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S 29			S 28
NW	SW	SE	NE
M.C.			

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Tree and Distances in Links.

M.C.			
S. 29			
B.T.			

Species H.P. Stump

Diameter 24"

Bearing N17°W

Distance .340h.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

R. T. DeFaut
Raymond T. DeFaut

(Signature)

Jr. Civil Engineer

(Title)

6-17-40

(Date)

M.C.

29 / 25

CLASS OF

Corner again.

Give any further facts which will aid in finding the

chain distant.

from which this Corner bears

South


side of

tree 8 inches diameter, on the

North

Metal Location: Post is on a

N. Pine



(Make sketch of topography near Corner)