

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

Posted 1/3

CORNERS OF THE PUBLIC SURVEY

T. 192N R. 28W 5 Mer.

1/4 Corner common to Sections 30, and 31



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Oak

Diameter 8" 6.5"

Bearing S(?)W S(?)E

Distance 1ch 1ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Henry K. ...
(Signature)


ENGINEER

(Title)

3/13/35
(Date)

PLANNED TO BE USED FOR
 THE PURPOSE OF
 THE STATE OF
 THE UNITED STATES

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a
 NONE



(Make sketch of topography near Corner)