

U. S. Department of Agriculture
FOREST SERVICE

Plotted 7-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 192N R. 23W 5TH Mer.

Corner common to Sections 1/4, 30, and 29



Corner consists of a Br cap 1" pipe (~~rod~~) in place
State condition good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

No
Var
Used.

<u>1/4 330</u>			
<u>B.T.</u>			

Species Aspen

Diameter 10"

Bearing S 16° W

Distance 373.6 links

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____


Daniel Rose Jr

(Signature)

Estimator

(Title)

Mar 27, 35
(Date)



Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this corner bears *right by corner*

side of Post

tree $3\frac{1}{2}$ inches diameter, on the *N. W.*

Metal Location Poster is on a *Scribed Post*



(Make sketch of topography near Corner)

T. 142N R. 28W Mer. T-5