

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N. R. 28W 5 Mer.

1/6 Cor. # 12 Corner common to Sections
32, _____, and _____



Corner consists of a 1" I.P. w/ brass Cap in place
State condition good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face of edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

C 5 1/6 532	C 5 1/6		
BT	32 B.T.		

Species R. Oak J.P. Pine

Diameter 14 12

Bearing S 40 1/2 W N 75 E

Distance 0.89 chs. 1.54 chs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H/ Carl E. Steadland

(Signature)

Foreman

(Title)

5/22/39

(Date)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears *N 40 1/2 E*

side of

tree *14* inches diameter, on the

Metal Location Poster is on a *R. Oak*



(Make sketch of topography near Corner)

Mer.

R. 28 W

T. 14 N

5

Y-7