

U. S. Department of Agriculture

FOREST SERVICE

*Dep  
4-9  
already posted*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 5th Mer.

S 1/16

Corner common to Sections

28, and 29

Corner consists of a G.L.O. monument ~~(not)~~ in place

State condition Excellent

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S	1/16	
29		28	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Edward Panek*  
Edward Panek

(Signature)

Junior Forester, P-1

(Title)

4/14/37

(Date)

