

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa*

NATIONAL FOREST

*Posted R-9 1933*

CORNERS OF THE PUBLIC SURVEY

T. *142* R. *28* S. *5* Mer.

Section *Section* Corner common to Sections *20, 21, 28, and 29*

Corner consists of a *G.L.O. Cap* (not) in place  
State condition *Good*

Dimensions above ground *4* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S	S	S
20	29	28	21

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



*T-42N  
R-28W  
S-21*

*B.T.*

*B.T.*



*B.T.*

Species *Ash Elm Maple*  
Diameter *13 inch 14 inch 10 inch*  
Bearing *N55°W S5°W N37°E*  
Distance *45 links 13 links 92 links*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*B. Hutchison*

(Signature)

*Mar. 27, 1935*

(Date)

*Estimator*

(Title)



U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

*R-9*  
*all ready Posted 2 of 3*

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 5th Mer.

Section Corner common to Sections

20, 21, 28, and 29 Iron

Corner consists of a G.L.O. Mon. & ~~stone~~ in place

State condition Excellent

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

142	28	
20	21	
29	28	
N	W	S

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



T142N  
R28W  
S28

T142N  
R28W  
S21



B.T.

B.T.

B.T.

B.T.

Species Elm Maple Maple Ash stump

Diameter 18" 8" 10" 15"

Bearing S25°W S81°E N40°E N47°W

Distance 15 lks. 89 lks. 92 lks. 54 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Edward Panek*  
Edward Panek

(Signature)

Junior Forester, P-1

(Title)

4/14/37

(Date)

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

Corner again.

Give any further facts which will aid in finding this

chains distant.


0 + 15

from which this Corner bears N 25° E

side of section corner

tree 18 inches diameter, on the south

Metal Location Poster is on a Elm



(Make sketch of topography near Corner)

R-9  
Mer.  
2072

T. 142 R. 28 5th

Form 874-B—Revised May, 1915  
 U. S. Department of Agriculture  
 FOREST SERVICE

172  
 2-7-37  
 R-9  
 2/3



Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 142N. R. 28W. 5th Mer.

Section Corner common to Sections  
30, 31, 32, and 33

Corner consists of a G.L.O. Monument (not) in place  
 State condition Excellent

Dimensions above ground 4 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	T142N R28W 528	T142N R28W 521	
B.T.	B.T.	B.T.	B.T.

Species	<u>Elm</u>	<u>Maple</u>	<u>Maple</u>	<u>Ash stump</u>
Diameter	<u>10"</u>	<u>8"</u>	<u>10"</u>	<u>15"</u>
Bearing	<u>S 85° W</u>	<u>S 81° E</u>	<u>N 40° E</u>	<u>N 47° W</u>
Distance	<u>15 lks.</u>	<u>89 lks.</u>	<u>92 lks.</u>	<u>54 lks.</u>

Do you believe this to be a genuine Land Office Corner? Yes  
 If not, why? \_\_\_\_\_

Edward Parke

(Signature)

4/14/37  
 (Date)

James Hunter P.  
 (Title)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which the corner bears *0715*

side of *Section corner*

tree *18* inches diameter, on the *South*

Metal Location Poster is on a *elm*



(Make sketch of topography near corners)

T. 142N. R. 28W. 5th P. Mer. R-9