

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

Posted 2-10

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 5 Mer.

W 1/6 Corner common to Sections 33, and 4

Corner consists of a Brass cap 6.0 (not) in place State condition Good

Dimensions above ground 14" inches Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

33		4	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?


R. D. W. Ecker

(Signature)

Estimator (Title)

3/20/35 (Date)

Corner again.
 Give any further information will aid in finding this
 from which this
 side of
 tree inches diameter, on the
 Metal Location Poster is on a
 Swamp no longer
 far poster



(Make sketch of topography near Corner)

T. 143 R. 28 Mer. 2-10