

U. S. Department of Agriculture

FOREST SERVICE

Plotted N-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142* R. *28* S. *5* Mer.

Meander Corner common to Sections
 _____, *21*, and *16 & Leech Lake*.

Corner consists of a *G.L.O.* _____ in place

State condition *Good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
16		21	
N	W	E	

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T-142 N
R-28 W
S-16
M.C.

T-142 N
R-28 W
S-21
M.C.

B.T.

B.T.

Species *Aspen* _____ *Oak* _____

Diameter *6 inch* _____ *10 inch* _____

Bearing *N45°E* _____ *S45°E* _____

Distance *60 links* _____ *50 links* _____

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

D. Hutchinson


(Signature)

3/27/35
(Date)

Estimator
(Title)

Found on Section line of
16, 21 at intersection with
Leech Lake.
Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142 R. 28 S. 5 Mer. N-9