

U. S. Department of Agriculture

FOREST SERVICE

Chippewa alluvial Pasture NATIONAL FOREST

*K-11*  
*Pasture*  
*Chippewa*

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 5th Mer.

CN 1/16 S16 Corner common to Sections

-----, -----, -----, and -----

Corner consists of a 1" I.P./ waxcap (not) in place


State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CN 1/16			
S 1/16			
B. T.			

Species Tamarack

Diameter 4"

Bearing N43° E

Distance 77 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

*A. C. Upham*  
A. C. Upham

(Signature)

Juni r Forester, P-1

(Title)

4/19/37

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

chains distant.

.77

from which this Corner bears


S 43° E

side of GN 1/16 S16

tree 4 inches diameter, on the

E

Metal Location Poster is on a 4" Tamarack (BT)



(Make sketch of topography near Corner)

T 142 R 28 5th Mer.

K-11