

U. S. Department of Agriculture
FOREST SERVICE

Chippewa

NATIONAL FOREST

Posted J-11

CORNERS OF THE PUBLIC SURVEY

T. *142* R. *28* S. Mer.

1/4 Corner common to Sections

9, and *16*

Corner consists of a *Galv. Brass Cap* (not) in place

State condition *Good*

Dimensions above ground *10"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>9</i>		<i>16</i>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4 Cor</i> <i>9</i> <i>142</i>
--

--

<i>1/4 Cor</i> <i>16</i> <i>142</i>

--

<i>28</i>

--

<i>28</i>

--

Species *Cedar* *Cedar*

Diameter *6"* *6"*

Bearing *N. 20° E* *S. 30° W*

Distance *12.415* *8.415*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____


3/29/35
(Date)

P. G. McEachin
(Signature)

Estimator
(Title)

(Make sketch of topography near Corner)

T 142 R 28 Mer. 5-11



Metal Location Poster is on a *Cedar* tree $\frac{1}{4}$ inches diameter, on the side of

from which this Corner bears $5.20^{\circ} W$

450 Mts. Chain distant.

Give any further facts which will aid in finding this

Corner again.

NE edge of cedar Swamp