

U. S. Department of Agriculture

FOREST SERVICE

P-13
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 28 W 5 Mer.

1/4 Corner common to Sections

21, and 22

Corner consists of a G.L.O. Cap (not) in place

State condition O.K.

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	21		22

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

B. Hutchinson

(Signature)

Estimator

(Title)

4/1/35 (Date)

Surrounding country is
7bx swamp with some brush.

This pole marks the spot
where the corner is to be found.
No B.T.'s located.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears —

side of pole

tree 3 inches diameter, on the North

Metal Location Poster is on a 5ft. pole



(Make sketch of topography near Corner)

T. 143N R. 28W 5 Mer. P. 13