

U. S. Department of Agriculture
FOREST SERVICE

Posted N-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142 N* R. *28 W* *5* Mer.
Section Corner common to Sections

16, *15*, *21*, and *22*

Corner consists of a *G.L.O. Cap* (~~not~~) in place

State condition *Good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

<i>S</i>	<i>S</i>	<i>S</i>	<i>S</i>
<i>16</i>	<i>21</i>	<i>22</i>	<i>15</i>

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--

<i>T-142 N</i>
<i>R-28 W</i>
<i>S-21</i>

<i>T-142 N</i>
<i>R-28 W</i>
<i>S-22</i>

--

--

<i>B.T.</i>

<i>B.T.</i>

--

Species *Aspen Oak*

Diameter *12 inch 10 inch*

Bearing *S. 530° E.*

Distance *45 links 1 chain & 85 links*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

L. D. Hutchinson

(Signature)

Estimator

(Title)

3/29/35
(Date)

Corner again.

Give any further facts which will aid in finding this

15 links ~~chains distant~~


from which this Corner bears

South

side of *Aspen*

tree 4 inches diameter, on the *South*

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)