

L-13

U. S. Department of Agriculture

FOREST SERVICE

*Posted*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5 Mer. Quarter Corner common to Sections

16, 15

Corner consists of a G.L.O. Cap. (~~not~~) in place

State condition O.K.

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	16		15
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	$\frac{1}{4}$		$\frac{1}{4}$
	S 16		S 15
	B.T.		B.T.

Species Maple Oak

Diameter 8 inch 16 inch

Bearing S 75° W N 38° E

Distance 100 links 95 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*S. Hutchins*

(Signature)


3/29/35  
(Date)

*Estimator*  
(Title)

Corner again.  
Located at corner of fence following section line N, then swinging East at quarter corner.

Give any further facts which will aid in finding this corner distant.

from which this Corner bears West  
side of Maple  
tree 14 inches diameter, on the West  
Metal Location Poster is on a Maple



(Make sketch of topography near Corner)