

U. S. Department of Agriculture  
FOREST SERVICE

*Posted 2/17*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *28W* S. *5* Mer.

*1/4* Corner common to Sections

*22*, and *23*

Corner consists of a *G.I.O. Cap* (not) in place

State condition *O.K.*

Dimensions above ground *8* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	22		23


N

W

S

E

NW

SW

SE

NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--

<i>1/4 S</i>
<i>22</i>

--

<i>1/4 S</i>
<i>23</i>

--

<i>B.T.</i>
-------------

--

<i>B.T.</i>
-------------

Species *Cedar* *Cedar*

Diameter *5 inch* *6 inch*

Bearing *W.* *S. 13° E.*

Distance *12 links* *25 links*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*L.B. Hutchinson*

(Signature)

*Estimator*

(Title)

*4/1/35*  
(Date)

Found in cedar swamp.  
An old blazed line runs  
approximately North & South  
along thru this corner

Corner again.

Give any further facts which will aid in finding this


line's exact distance.

From which this Corner bears  $N13^{\circ}W$

side of Cedar

tree 6 inches diameter, on the North

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)