

U. S. Department of Agriculture  
FOREST SERVICE

P. 21  
x-21

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 142 R. 54 Mer.

1/4 Corner common to Sections  
35, and 36



Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.



Species 0915 Maple

Diameter 16 1/2"

Bearing N74 E W

Distance 526 25

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

G. Sherman

(Signature)

3/5/35

(Date)


Engineer

(Title)

SECTION 35  
 T. 142 N.  
 R. 25 W.  
 S. 36

Corner again.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a *Oak-Beaving Tree*



(Make sketch of topography near Corner)