

U. S. Department of Agriculture  
FOREST SERVICE

P. 21  
4-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 Mer.

S 1/16 Corner common to Sections  
35, 36, and

Corner consists of a (not) in place  
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species Elm

Diameter 10"

Bearing N 40 E

Distance 554

Do you believe this to be a genuine Land Office Corner?

If not, why?

G. Sherman

(Signature)


3/5/32

(Date)

Engineer

(Title)

Metal Location Poster is on a *TCI Post*  
 tree *inches diameter*, on the  
 side of *from which this Corner bears*  
 chains distant. *Give any further facts which will aid in finding this*  
 Corner again.



(Make sketch of topography near Corner)