

U. S. Department of Agriculture  
FOREST SERVICE

J-21

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 142 R. 28 Mer.


Sec Corner common to Sections  
11, 12, 13, and 14

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.



Species ELM

Diameter 17

Bearing S 50 E

Distance 105 L

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

G. Sherman

(Signature)

Engineer

(Title)

3/6/35

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

..... from which this Corner bears *WEST*

side of

..... inches diameter, on the *EAST*

Metal Location Poster is on a *Fence Post*



(Make sketch of topography near Corner)