

U. S. Department of Agriculture

FOREST SERVICE

W-22

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142-N R. 28-W 5th Mer.

Corner common to Sections 16, 36, and

Corner consists of a 4x4 post in place State condition

Dimensions above ground 1 1/4 x 1 1/4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N 44 1/2° S 36			
BT			

Species Ash St.p.

Diameter 8"

Bearing N 77° E

Distance 21.5

Do you believe this to be a genuine Land Office Corner?

If not, why?

Amel Ross

(Signature)

Estimator

(Title)

Mar 18, 1935

(Date)


Section 34

Section 35

Corner again.  
Posterior view of corner

Give any further facts which will aid in finding this  
chain distant:  
from which this corner bears  
side of  
tree inches diameter, on the

Metal Location Poster is on a *None Used*



(Make sketch of topography near corner)

T. 142 N. R. 27 E. S. 5 Mer.