

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Noted V-22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 23 W 5th Mer.



1/16 Corner common to Sections 25, and 36

Corner consists of a wood Post (~~rod~~) in place
 State condition fair

Dimensions above ground 3" square, 36" high
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Dead Tree
 Diameter 4"
 Bearing S 25° E
 Distance 63.4

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? But Brass cap cannot be found.

David J. ...
 (Signature)
Mar 18, 35 (Date)
Estancio
 (Title)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *None used*



(Make sketch of topography near Corner)

T. 142 N. R. 27 + 28

Mer. V-22