

R-22

U. S. Department of Agriculture

FOREST SERVICE

Tested

Chippawa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *28W* *5th* Mer.

1/4 Corner common to Sections

24, and *25*

Corner consists of a *Br Cap Pipe* (~~set~~) in place



State condition *bent*

Dimensions above ground *12* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Balsamif*

Diameter *1 1/2"*

Bearing *S 21° W*

Distance *41.4x*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Daniel Rose
(Signature)

Mar 19 35 Estimator
(Date) (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

N 1/4


from which this Corner bears

N 37° E

side of *Tree*.

tree 8' inches diameter, on the *NE*

Metal Location Poster is on a *W.L. line*



(Make sketch of topography near Corner)

T. 142 N.

R. 27 E.

575

Mer.

R-22