

U. S. Department of Agriculture
FOREST SERVICE

A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N. R. 28 Mer.

Corner common to Sections 36, and 1



Corner consists of a (not) in place State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm

Diameter 12" 10"

Bearing S85W N25W

Distance 65L 145L

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

G. Sherman

(Signature)

3/16/25

(Date)

Engineer

(Title)

.....
.....
.....
.....
.....
.....
.....
.....

Corner again.


Give any further facts which will aid in finding this

..... chains distant.

..... 30
..... from which this Corner bears South

..... side of Post
..... 7 inches diameter, on the North

Metal Location Poster is on a 721 Post



(Make sketch of topography near Corner)

Mer. A-23

I. 14 R. 28