

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

Posted 7-24

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5th Mer.

1/4 Corner common to Sections

Corner consists of a 1" pipe in place


State condition good

Dimensions above ground 4" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Redstart Tree

Diameter 2 1/2 3

Bearing S 35° E N 64° W

Distance 32 174

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Daniel Rose Jr.

(Signature)

Compassman


(Title)

Mar 24, 35

(Date)

SE 1/4 336

Corner again.
Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a
None used



(Make sketch of topography near Corner)