

U. S. Department of Agriculture
FOREST SERVICE

X-6,7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5 Mer.

164 Corner common to Sections
32, _____, _____, and _____

Corner consists of a 1" I.P. w/ brass Cap (~~rod~~) in place



State condition good

Dimensions above ground 6" _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species None _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl E. Steadland

(Signature)

Foreman

(Title)

5/23/39

(Date)

Corner again.

Give any further facts which will aid in finding this


0.12 chains distant.

from which this Corner bears 5/10° W

side of

tree 6 inches diameter, on the

Metal Location Poster is on a R. Oak



(Make sketch of topography near Corner)

Mer.

X-6,7

5

R. 28 W

T. 142 N