

U. S. Department of Agriculture
FOREST SERVICE

X-7,8

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5 Mer.

464
32 Corner common to Sections
32, _____, and _____



Corner consists of a 1" I.P. w/ brass cap (not) in place
State condition Good

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species None

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

B. Carl E. Steadland

(Signature)

Foreman

(Title)

5/22/39

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


0.09

from which this Corner bears 532.7

side of

tree 6 inches diameter, on the

Metal Location Poster is on a W Oak 6"



(Make sketch of topography near Corner)

Mer.

5

R. 28 W

T. 142 N

X-78