

U. S. Department of Agriculture  
FOREST SERVICE

173/39  
725/10  
RP

14-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 29W 5th Mer.

5 1/4 Corner common to Sections  
11, and 12


Corner consists of a 1" Iron (not) in place  
State condition Good

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species R. OAK W. OAK

Diameter 16" 12"

Bearing N 33° E S 42° E

Distance 68.1 kts. 1.61 Chs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

G. C. Upham  
(Signature)  
Lincoln & Trustee P-1  
(Title)

4/13/37  
(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


68 1/2' chains distant.

from which this Corner bears S 33° W

side of

tree 16 inches diameter, on the E

Metal Location Poster is on a Red Oak



(Make sketch of topography near Corner)

H-21  
Mer.

5 7/8

T. 142 N. R. 29 W.