

U. S. Department of Agriculture

FOREST SERVICE

L-23,24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. E. 9 W. Mer.

A.M.C. Corner common to Sections

13, and

Corner consists of a 1" Iron pipe <sup>W/loop</sup> (not) in place


State condition Good

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

A.M.C. S. 13

B.T.

Species W. PAK.

Diameter 7 1/4"

Bearing S. 46° E

Distance 1.13 cbs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. C. Upham (Signature)

4/13/37 (Date)

J. C. Upham (Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears N. 41° W.

side of corner (A.M.C.)

tree of 4 1/2 inches diameter, on the E

Metal Location Poster is on a white oak



(Make sketch of topography near Corner)

T. 143 N. R. 29 W. 5th Mer.

7-23-24