

U. S. Department of Agriculture

FOREST SERVICE

173  
7-28-37  
P  
M/10

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *30W* *5th* Mer.

*SW 1/4* Corner common to Sections *16*, and

Corner consists of a *1" I.M. w/ brass cap* (not) in place



State condition *Good*

Dimensions above ground *7* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen Aspen*

Diameter *10 6*

Bearing *N36W N47E*

Distance *0.24 0.75*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadman*

(Signature)

*Aug 27, 1936*

(Date)

*Donald J. ...*

(Title)

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears side of

tree 10 inches diameter, on the

Metal Location Poster is on a *Logan*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R.

Mer.

M-10