

U. S. Department of Agriculture

FOREST SERVICE

T-12
[Handwritten initials]

Chippewa NATIONAL FOREST

already Posted

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 30 ~~22~~ 5th Mer.

CE 1/16 Corner common to Sections
 28, _____, and _____

Corner consists of a 1" I.P. w/cap (set) in place



State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R. Moore
 R. Moore

(Signature)

1/13/37

(Date)

Asst. Ldr., F-48

(Title)

Corner again.

Give any further facts which will aid in finding this

chain distant.


N 72 W

from which this Corner bears

side of

tree 10 inches diameter, on the

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 142 R. 30 5th Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

T-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142 N* R. *30 W* S. *52* Mer.

CE 1/16 Corner common to Sections
28, _____, and _____



Corner consists of a *1" I.P. W/cap* (not) in place
 State condition *Good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

1/3/37
 (Date)

R Moore
 (Signature)
Asst Sdr
 (Title)

U. S. DEPARTMENT OF THE INTERIOR

COMMISSION OF THE LAND OFFICE

Corner again.

Give any further facts which will aid in finding this


chain distant.

From which this Corner bears
side of

N 71 W

tree inches diameter, on the

Metal Location Poster is on a *10*
Post



(Make sketch of topography near Corner)

T 14 2 N R 30 W
5th
T-12