

U. S. Department of Agriculture
FOREST SERVICE

N-13
9-23-36
[Signature]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 30W 5th Mer.

Corner common to Sections 15, 16, 21, and 22



Corner consists of a 2" I.M. N/line Cap (not) in place
State condition Good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? [Signature]

If not, why? _____

Carl Steadland

(Signature)

Aug. 25, 1936
(Date)

Const. Sec
(Title)

SECTION NAME

NUMBER OF THE SHEET IN THE SET

DATE OF SURVEY

Corner again.

Give any further facts which will aid in finding this

chain's distant.

from which this Corner bears

side of

at corner

tree 4 inches diameter, on the

following
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer.

R

T