

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14RN* R. *31W* *5th* Mer.

East 1/6 Corner common to Sections

7, and *18*

Corner consists of an *iron pipe* (not) in place

State condition *fair*

Dimensions above ground *2 x 20* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>None</i>		

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>None</i>

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

County, resurvey corner

Dorman Sutton

(Signature)

3-15-35

(Date)

Engineer

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

H. 10


from which this Corner bears

S 58° W

side of *post*

tree *6* inches diameter, on the *W. 3/4*

Metal Location Poster is on a *Post (near road)*



(Make sketch of topography near Corner)

T. 112 N. R. 51 W. 5th Mer. J-4