

U. S. Department of Agriculture

FOREST SERVICE

P-5 *[Handwritten initials]*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 31 W. 5th Mer.

1/4

Corner common to Sections

19, 20, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a 2" Iron Pipe (~~Set~~ in place

State condition Good

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	None		

N W S E

	None		

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? County corner

*[Handwritten Signature]*

Ed. Panek

(Signature)

Junior Forester

(Title)

3/2/38

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

chains distant.

1.15


from which this Corner bears S. 41° W.

side of 1/4 corner

tree 6 inches diameter, on the North

Metal Location Poster is on a

Oak



(Make sketch of topography near Corner)

T. 142 N. R. 31 W. 5th Mer.

P-5