

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

0-524

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 31 W. 5th Mer.

N. 1/16 Corner common to Sections
19, 20, and

Corner consists of a 2" Iron Pipe ~~flag~~ in place

State condition Good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		None	
--	--	------	--

N W S E

		None	
--	--	------	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

Ed Panek

Ed Panek

(Signature)

Junior Forester

(Title)

3/2/38

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.16


from which this Corner bears S. 63° W.

side of N. 1/16 corner

tree 3 inches diameter, on the North

Metal Location Poster is on a

Oak



(Make sketch of topography near Corner)

T. 142 N. R. 31 W. 5th Mer.