

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST *1872*

CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *31W* *5th* Mer.

Quarter Corner common to Sections

_____, _____, *16*, and *17*

Corner consists of a *Nat located* (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>Blaze</i>			

Species *Aspen* _____

Diameter *6"* _____

Bearing *N 76° E* _____

Distance *63* _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Co. Resurvey corner.

Dorman J. Sutton

(Signature)

Engineer

(Title)

3-14-35

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears 576 W

side of tree

tree 6 inches diameter, on the S W

Metal Location Poster is on Aspen



(Make sketch of topography near Corner)

T. 142 N R. 31 W S 4 Mer. 4-9