

U. S. Department of Agriculture  
FOREST SERVICE

123  
728-27  
E-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

Section Corner common to Sections

2, 3, 10, and 11

Corner consists of a 2" I. P. Brass Cap (set) in place

State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

			T142N R31W				
			S3   S2				
			S10   S11				
			1917				
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species	R. Oak	R. Oak	Aspen
Diameter	8	8	7
Bearing	N44E	N34W	S76 $\frac{1}{2}$ N
Distance	22	36	17

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Carl Steadland  
(Signature)

July 2, 1935  
(Date)

C. F.  
(Title)

Corner again.  
 Give any further facts which will aid in finding this  
 0.22 chains distant.  
 from which this Corner bears S44W  
 side of  
 three 8 inches diameter, on the  
 Metal Location Poster is on a Red Oak

0.36 chs.  
 from which the corner bears S34E  
 Poster on Red Oak, 8" Diameter,

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

E-17

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 31 W 5th Mer.

Section Corner common to Sections

7, 8, 10, and 11


Corner consists of a 2 1/2" I.P. Brass Cap in place

State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION




N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Red Oak Red Oak Aspen

Diameter 8 8 7

Bearing N44 E N34 W S76 1/2 W

Distance 22 36 17

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

July 2, 1935 (Date)

(Signature)

Corner on *Old Post. 8' diameter,*  
from *west* the corner,  
from *gate* 0.36 *etc.*

Corner again.  
Give any further facts which will aid in finding this  
0.22 chains distant.  
from which this Corner bears  
*SW N*  
side of  
tree 8 inches diameter, on the  
Metal Location Poster is on a  
*Old Post*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

*T. HAN R. 31 W*  
*5th*  
Mer. *E-17*