

U. S. Department of Agriculture  
FOREST SERVICE

173  
7-22-35  
E-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

W 1/16 Corner common to Sections  
2, and 11

Corner consists of a 1" I.P. Brass Cap (not) in place  
State condition Good

Dimensions above ground 12" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

			W 1/16 S2				
			S11				
			1917				
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species No. B. I's found

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

(Signature)


July 2, 1935

(Date)

C.F.

(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a Red Oak

tree 6 inches diameter, on the

side of

from which this Corner bears S67E

0.217 chains distant.

Give any further facts which will aid in finding this

Corner again.