

U. S. Department of Agriculture

FOREST SERVICE

P
C-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 31W 5th Mer.

1/4 Corner common to Sections

11, and 12
Corner consists of a 1" I.P. Brass Cap (not) in place

State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

			1/4					
			S 11		S 12			
N	W	S	E 1917	NW	SW	SE	NE	

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species R. Oak Stump

Diameter 6"

Bearing N 77 E

Distance 26

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

(Title)

June 25, 1935
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

007

from which this Corner bears

S 27 E

side of

tree inches diameter, on the

Metal Location Poster is on a

Copper

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R.

Mer.

5-21