

U. S. Department of Agriculture
FOREST SERVICE

1227
778-37
OK
E-21
X

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

Section Corner common to Sections

1, 2, 11, and 12

Corner consists of a 2" I.P. Brass Cap (not) in place

State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

			T142N R31W				
			S2 S1				
			S11 S12				
N	W	S	E 1917	NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species R. Oak R. Oak R. Oak R. Oak

Diameter 6 5 7 6

Bearing N20E NW S60 1/2 W S64E

Distance 33 25 43 36

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

(Signature)

June 25, 1935

C.F.

(Date)

(Title)

Corner again.
Poster on 7" Red Oak, from which corner bears N60¹/₂E 0.43 Chs.

Give any further facts which will aid in finding this chains distant.

from which this Corner bears S20W side of tree 6 inches diameter, on the Metal Location Poster is on a Red Oak

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)