

U. S. Department of Agriculture  
FOREST SERVICE

*Copied  
Printed  
0-21/36*

----- NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 142 R. 31 Mer. 5

----- Corner common to Sections  
1, 2, -----, and -----

Corner consists of a iron corner (not) in place  
State condition -----

Dimensions above ground ----- inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of ----- is located on a hill

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

-----

-----

----- (Signature) -----


----- (Date) -----

----- (Title) -----

2 HIGHWAY 18 ON STUMP N 50 W 35 14  
1 HIGHWAY 24 ON STUMP E 90 30 14

Corner again.  
Iron

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)