

Form 574-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

*Copied
Posted
5/36
A-21*

NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 142 R. 31 Mer. 5
4 Sec. Corner common to Sections

1, 2, and _____
Corner consists of a iron stake (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species norway, norway _____

Diameter 24 18" _____

Bearing E-90 N-50 W _____

Distance 30-ft 35-ft _____

Do you believe this to be a genuine Land Office Corner? _____


If not, why? because old corner have been destroyed

(Signature)

(Date)

(Title)

Metal Location Poster is on a
 three inches diameter, on the
 side of
 from which this Corner bears
 chains distant
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)