

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

*Copied  
Posted  
9/34.  
E23*

NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 142 R. 31 S. 5 Mer.

Corner common to Sections

1, 12, and \_\_\_\_\_

Corner consists of a iron along side of tam (not) in place

State condition \_\_\_\_\_

Dimensions above ground, iron 1" tam inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located in swamp

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species Tam. TAM.

Diameter 3" 3"

Bearing N 45 E W 90

Distance 4 ft 2ft

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

Give any further facts which will aid in finding this  
 Corner again.

from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)