

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142 N.* R. *31 W.* *5th* Mer.


Meander Corner common to Sections
 _____, _____, _____, and _____

Corner consists of a *1" I.P. Brass Cap* (not) in place
 State condition *Good*

Dimensions above ground *6 7/8* inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>CMCS14BT</i>	<i>S11BT</i>		

Species *N.P. Stump* *N.P. Stump*
 Diameter *20"* *22"*
 Bearing *S68 1/2 W* *N30 1/2 W*
 Distance *5 1/2* *14 1/2*

Do you believe this to be a genuine Land Office Corner? *Yes*
 If not, why? _____

Carl Steadland

 (Signature)
June 18, 1935

 (Date) _____ (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T-1819 Mer.

T. 142 R. 31 W.