

U. S. Department of Agriculture
FOREST SERVICE

123-37
7-18-35
992

J-2223

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY


T. 142N R. 31W 5th Mer.
1/64

Corner common to Sections
13 (9.97 Chs. W. of $\frac{1}{4}$ Secs. 12 & 13)

Corner consists of a "I. P. Brass Cap" in place
State condition Good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species No. B. I.'s on 1/64 corners _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

June 18, 1935

(Date)

C. F.

(Title)

U. S. Department of Agriculture
Forest Service

FOREST LOCATION POSTER

FOR THE LOCATION OF METAL POSTERS

Corner again.
Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

N77E


0.107

side of

tree 5 inches diameter, on the

Metal Location Poster is on a

Aspen



(Make sketch of topography near Corner)

Mer.

T. 142 R. 31 W. S4

5-22/33