

123
7-28-37
C.S.

U. S. Department of Agriculture

FOREST SERVICE

K-22,23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31 W. 5th Mer.

1/64

Corner common to Sections

13 (9.93 chs. W. of C N, and 1/16 S.13)

Corner consists of a 1" I.P. Brass Cap in place

State condition Good

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

				AP5 TR 1565				
N	W	S	E	1919	NW	SW	SE	NE

Mound of _____ is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter No B. T's on 1/64 corners

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

(Signature)

June 17, 1935

(Date)

C. F.

(Title)

Department of Agriculture
Bureau of Plant Industry
Washington, D. C.

Corner again.
Give any further facts which will aid in finding this
chain distant.
0.057
from which this Corner bears
S65°W
side of
tree 5" inches diameter, on the
Metal Location Poster is on a Black Spruce

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. W. R. 31 W. S. 5
Mer. 2223