

U. S. Department of Agriculture

FOREST SERVICE

N-29, 21

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 31 W. 5<sup>th</sup> Mer.

Meander

Corner common to Sections

14, and 13

Corner consists of a 1" I.P. Brass Cap (not) in place


State condition Good

Dimensions above ground 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J.P. J.P.

Diameter 9 9

Bearing N59E S83E

Distance 47 12

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Carl Steadland

(Signature)

June 13, 1935

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.12

from which this Corner bears

*N 83° W*

side of

tree 9 inches diameter, on the

Metal Location Poster is on a *Rock*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

*N-2021*

T. 142 N R. 31 W S. 5 Mer.