

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

20-21 P

CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *31W* *5th* Mer.

Meander Corner common to Sections

23, and *24*

Corner consists of a *"S.P." Brass Cap* (not) in place


State condition *Good*

Dimensions above ground *4"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *J.P.* *J.P.*

Diameter *7"* *5"*

Bearing *S53 1/2 E* *N33W*

Distance *39* *16*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadland
 (Signature)
June 13, 1935
 (Date)
102
 (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant. 0.16

from which this Corner bears @ 33E

side of

tree 5" inches diameter, on the

Metal Location Poster is on a *Jack Pine*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

NO-21

Mer.

SR

T. 142N R. 31W