

U. S. Department of Agriculture
FOREST SERVICE

D.R.
COPIES

P
A-1

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143-144 R. 25-26 5th. Mer.

section Corner common to Sections
36, 31, 1, and 6

Corner consists of a Cedar post (not) in place

State condition good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

N.F. Shaw

(Signature)

ENGINEER

(Title)

Mar. 7, 1935

(Date)

