

U. S. Department of Agriculture
FOREST SERVICE

P

0-6

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 75 Mer.

1/16 # 4 Corner common to Section
20, and


Corner consists of a Iron Pipe (~~rod~~) in place
State condition 1 1/2" pipe

Dimensions above ground 3' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? No Witness Trees

G. Sherman

(Signature)

Engineer

(Title)

3/7/35

(Date)

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

..... from which this Corner bears 540 W

side of

..... inches diameter, on the N.W

Metal Location Poster is on a **TEL. POST**



(Make sketch of topography near Corner)