

U. S. Department of Agriculture

FOREST SERVICE

P
N-13

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 25 5 Mer.
section Corner common to Sections
16, 15, 21, and 22

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Cedar Stump
Diameter 14" D.B.H.
Bearing S.E.
Distance 40 links

Do you believe this to be a genuine Land Office Corner? NO

If not, why? See Copy

Norman F. Shaw

(Signature)

Mar. 8, 1935

(Date)

Engineer

(Title)

U. S. Department of Agriculture
FOREST SERVICE

P
N-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 25 5 Mer.
Sec. Corner common to Sections
16, 15, 21, and 22

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Cedar STUMP
Diameter 14" D.B.H.
Bearing S.E.
Distance 20 LINKS

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

Norman F. Shaw

(Signature)

Mar. 8-35
(Date)

Engineer
(Title)

