

Form 874-8—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

*Banner*

*PP*

*A-13*



*Chippewa* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. *143* R. *26* S. *5* Mer.

*Section* Corner common to Sections  
*3*, and *4*

Corner consists of a *Waeder post* (not) in place  
State condition *Good*

Dimensions above ground *36* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*H. A. Brills*

(Signature)

*7/26/34*

(Date)

*C. O. P.*

(Title)


CONSTITUTIONAL TOWER

CORNERS OF THE TOWER

Corner again.

Give any further facts which will aid in finding this  
CHAINING DISTANT  
CARDINAL POSITION  
DIAGONAL POSITION

from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a  
No. 24



(Make sketch of topography near Corner)

T. 143N R. 26W S. 24 Mer.